

Before



After



This is dragline floor in a local coal mine. It had a surface that was very hard to maintain, lifting up and was slippery when it was cleaned. We sprayed the floor in Duraspray and added a 36-grit aggregate for a slip resistant finish.

