


Before

Here we have a commercial kitchen at Wangi.



There was an existing epoxy floor in poor condition that needed rejuvenating.

After



The floor took 2 days two to complete with outstanding results. The cooking equipment was not able to be removed so we encapsulated the legs of the equipment which still complied with the health department regulations.

