


Before



After



Here our client needed a protective coating that could, not only take an impact from lifting these with an overhead crane, but also protect from chemical exposure. We sandblasted these arms to remove all old paint and contaminate. Then we sprayed the arms with Tuff Stuff for the best result. Now it is both impact and chemical protected.

