

Before



After



This floor is at a commercial kitchen at B.H.P. Wollongong. The floor had lino on it and had to be removed. Before spraying we recovered the entire floor which was 142 square metres. The project took 4 days to complete. It was sprayed with Durabond at approximately 4-5mm thick with a slip resistant finish.

