



Before



After



These bearing cases are fully submerged in water all the time; the engineering company needed a solution to the rusting and corrosion on the exterior of these casings. We sandblasted the outer casing and then primed them with a 251 primer. After curing we sprayed them with Duraspray for a sealed chemical and waterproof covering.

