

Before



After



This is a box gutter that was continuously leaking at Sanitarium Health Foods. The gutter was stainless steel and they found no answer to there problem. We sprayed the gutter with tuff stuff and sealed all the leaks. There was no down time for the company and was completed over two days.

