


Before



After



This is a Hydrochloric acid tank farm at Bluescope Steel. They had a problem with concrete corrosion and pipes rusting out. Also they needed to remain in production with no down time. We repaired areas effected by corrosion and sealed the whole containment area. The acid farm was around 800 square metres and we completed it in 6 days.

